

General Environmental Incident Summary

Incident: 5248 **Date/Time Notice:** 10/12/2016 1100 **DEM Incident No:**

Responsible Party: Nodak Electric

Date Incident: 10/12/2016 **Time Incident:** 10/3/2016 **Duration:** 20 days

County: Grand Forks **Twp:** 152 **Rng:** 51 **Sec:** 12 **Qtr:** NW NW

Lat: 48.00509 **Long:** -97.12870 **Method:** Interpolation from map

Location Description: Address is 1381 23re Avenue NE Grand Forks, ND 58201

Submitted By: Dan Schaefer

Affiliation: Employee

Address: 4000 32nd Ave S

City: Grand Forks

State: ND

Zip:

Received By:

Contact Person: Dan Schaefer
4000 32nd Ave. S.
Grand Forks, ND 58208

Distance Nearest Occupied Building: 2 Feet

Release Contained: Yes

Type of Incident: Transformer leak

Description of Released Contaminant: Mineral oil

Volume Spilled: 5.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Transformer had a gasket that was defective and caused oil to leak out.

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Soil was saturated by oil. We replaced with clean soil.

Action Taken or Planned:

The spill did not need to be contained as it had soaked in the soil. We removed oil soaked soil and replaced with dry soil

Wastes Disposal Location: City of Grand Forks landfill

Agencies Involved:

Updates

Date: 10/14/2016 **Status:** Correspondence

Author: Tintes Schiwal, Emily

Updated Volume:

Notes:

The report was vague on some information, so I requested a few details from the staff at Nodak and will update this report after I get more information.

Date: 10/14/2016 **Status:** Reviewed - Assigned to NDDoH Division

Author: Souder, Taylor

Updated Volume:

Notes:

Report has been forwarded to the Division of Waste Management within the NDDoH.